



INSPECTION REPORT

5080 Majestic View Rd, Coul
JOBSITE ADDRESS CITY STATE ZIP

DEPTH OF SCUM: 4"
(IF OVER 3-5 INCHES-TANK SHOULD BE PUMPED)

SEWAGE PUMP SYSTEM: YES ☐ NO ☒

TYPE OF TANK: CONCRETE ☒ POLY ☐ OTHER ☐

PUMP TANK SIZE

APPROX SIZE OF TANK: 1200

DOES PUMP SYSTEM WORK

CONDITION OF TANK: GOOD ☒ FAIR ☐ POOR ☐

DOES ALARM WORK: YES ☐ NO ☐

DEPTH OF SOIL TO TANK: 14"

RISERS ON PUMP TANK: YES ☐ NO ☐

RISERS: yes- Concrete Lids at Surface

CONDITION OF LIDS: OK

NUMBER OF LIDS: ONE ☐ TWO ☒ FOUR ☐

EFFLUENT FILTER: YES ☒ NO ☐ SIZE 6"

INLET BAFFLE OR SANITARY T: OK ☒ BROKEN ☐ MISSING ☐

TYPE OF BAFFLE: ABS ☒ CONCRETE ☐ PVC ☐ CLAY ☐ OTHER

NOTE: IF INLET BAFFLE OR T IS MISSING OR BROKEN ABOVE INLET PIPE, THERE WILL BE NO SCUM LAYER ON TOP. SLUDGE MUST BE CHECKED ON BOTTOM (SHOULD NOT BE OVER 6 INCHES)

OUTLET BAFFLE OR SANITARY T: OK ☒ BROKEN ☐ MISSING ☐

TYPE OF BAFFLE: ABS ☐ CONCRETE ☐ PVC ☒ CLAY ☐ OTHER

NOTE: IF OUTLET BAFFLE IS BROKEN BELOW OUTLET FLOW OR MISSING, THERE WILL BE PROBABLE SCUM IN FIELD, AND SLOW, IF ANY, LEACHING ACTION.

WASTEWATER LINE: OK ☒ SLOW ☐ PLUGGED ☐ NOBODY HOME ☐

HOUSE VACANT: YES ☐ NO ☒

RECOMMENDATION FOR TANK: OK ☐ PUMP ☒ REPAIR ☐

RECOMMENDATIONS: Pumped tank on 11-2-22
Ran Water out leach field for 20 Min. Leachfield
is Accepting Water at this time.
Cleaned 6" outlet filter

Mike Jly 11-2-22
INSPECTED BY DATE

TO WHOM IT MAY CONCERN:


It is my **OPINION** that this individual sewage-disposal system with recommended repairs (if any) and proper maintenance **can be expected** to function satisfactorily and **is not likely** to create unsanitary conditions.

Nick Fly
TECHNICIAN

11-2-22
DATE

PLEASE NOTE:

THIS CERTIFICATION IN NO WAY CONSTITUTES A WARRANTY OR GUARANTEE ON THIS SUBJECT SEPTIC SYSTEM. THIS CERTIFICATION ONLY REPRESENTS MY OWN EDUCATED OPINION, THEREFORE I CANNOT BE HELD RESPONSIBLE FOR ANY FUTURE MALFUNCTIONS OR BREAKAGE OF THE SYSTEM. THIS DISCLAIMER RELEASES SWEET SEPTIC INC. AND MYSELF OF ANY LIABILITY DUE TO ANY MALFUNCTIONS, BREAKAGE OR FAILURE OF THIS SYSTEM.





SWEET SEPTIC, INC.
5701 MOTHER LODE DRIVE
PLACERVILLE, CA 95667
(530) 622-8768

INVOICE

11/2/12 88598

ORDER NO.

INVOICE DATE

11/2/12 Mike

DATE SHIPPED

SHIPPED VIA

(916) 715-3373

NO. PCS.

WT.

FOB

TERMS

COD

SOLD TO

SHIPPED TO

Betty Smith
5080 majestic View Rd
COO1

QUANTITY	UNIT	DESCRIPTION	UNIT PRICE	TOTAL PRICE
		Inspection Pump Job		150
		DUG UP Labor 115/HR		495-
		Inspected and Pumped out Both Sides of 1200 gallon tank. Cleaned 6' filter #385915		
		Paid CK #14800		
		Total		\$ 645.00

722 NOV 2 AM 7:57